

L Number	Hits	Search Text	DB	Time stamp
40	2	("6587909").PN.	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/09/02 21:44
-	0	last-first\$.in.	USPAT; US-PGPUB	2003/08/19 12:42
-	2	ep-804933-\$.did.	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2003/08/20 09:16
-	15898	710/\$.ccls.	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2003/08/19 15:54
-	46	(hot live) same (plug\$3 swap\$3 insert\$3 add\$3 remov\$3 replac\$3) same (clock clk) same synchroniz\$5	USPAT; US-PGPUB	2003/08/19 12:44
-	60	(hot live) same (plug\$3 swap\$3 insert\$3 add\$3 remov\$3 replac\$3) same (clock clk) same synchroniz\$5	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2003/08/19 15:53
-	15	(slot same (card device interface)) and ((hot live) same (plug\$3 swap\$3 insert\$3 add\$3 remov\$3 replac\$3) same (clock clk) same synchroniz\$5)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2003/08/19 15:54
-	1389	(plug\$3 swap\$3 insert\$3 add\$3 remov\$3 replac\$3) same (clock clk) same ((synchroniz\$5 synchronous) same bus)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2003/08/19 15:54
-	0	710/\$.ccls. and ((slot same (card device interface)) and ((plug\$3 swap\$3 insert\$3 add\$3 remov\$3 replac\$3) same (clock clk) same ((synchroniz\$5 synchronous) same bus)))	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2003/08/20 12:08
-	295	(slot same (card device interface)) and (plug\$3 swap\$3 insert\$3 add\$3 remov\$3 replac\$3) same (clock clk) same ((synchroniz\$5 synchronous) same bus))	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2003/08/19 15:55
-	190	convert\$3 and ((slot same (card device interface)) and ((plug\$3 swap\$3 insert\$3 add\$3 remov\$3 replac\$3) same (clock clk) same ((synchroniz\$5 synchronous) same bus)))	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2003/08/19 15:56
-	231	710/\$.ccls. and ((plug\$3 swap\$3 insert\$3 add\$3 remov\$3 replac\$3) same (clock clk) same ((synchroniz\$5 synchronous) same bus))	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2003/08/19 15:58
-	17	710/301-304.ccls. and ((plug\$3 swap\$3 insert\$3 add\$3 remov\$3 replac\$3) same (clock clk) same ((synchroniz\$5 synchronous) same bus))	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2003/08/19 16:52
-	8	710/301-304.ccls. and (convert\$3 same signal) same (synchronous synchron\$5) same bus	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2003/08/20 12:03
-	48	710/301-304.ccls. and (convert\$3 same signal) and ((synchronous synchron\$5) same bus)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2003/08/19 16:59

-	0	wo-92/15959-\$.did.	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2003/08/20 09:17
-	0	WO-92/15959-\$.did.	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2003/08/20 09:17
-	0	WO-15959-\$.did.	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2003/08/21 08:56
-	2	WO-9215959-\$.did.	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2003/08/20 09:17
-	45	710/301-304.ccls. and (synchronous synchron\$5) same bus same ((clock clk) near6 signal)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2003/08/20 12:04
-	46	710/301-304.ccls. and ((slot same (card device interface)) and ((plug\$3 swap\$3 insert\$3 add\$3 remov\$3 replac\$3) same (clock clk) and ((synchroniz\$5 synchronous) same bus)))	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2003/08/20 12:10
-	10	(US-6564279-\$ or US-6418492-\$ or US-6516365-\$ or US-6473822-\$ or US-6108731-\$ or US-6098132-\$ or US-6338107-\$ or US-6202109-\$ or US-6272574-\$).did. or (WO-9215959-\$).did.	USPAT; EPO	2003/08/21 14:06
-	46	710/301-304.ccls. and ((slot same (card device interface module)) and ((plug\$3 swap\$3 insert\$3 add\$3 remov\$3 replac\$3) same (clock clk) and ((synchroniz\$5 synchronous) same bus)))	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2003/08/20 15:44
-	234	channel and (710/\$.ccls. and ((slot same (card device interface)) and ((plug\$3 swap\$3 insert\$3 add\$3 remov\$3 replac\$3) same (clock clk) and ((synchroniz\$5 synchronous) same bus))))	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/09/02 08:23
-	0	710/301-304.ccls. and (slot and (card device interface module)) and (plug\$3 swap\$3 insert\$3 add\$3 remov\$3 replac\$3) and ((clk clock) near10 select\$3)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2003/08/21 17:03
-	45	710/301-304.ccls. and (slot same (card device interface module)) and (plug\$3 swap\$3 insert\$3 add\$3 remov\$3 replac\$3) and ((clock clk) near10 select\$3)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2003/08/20 16:04
-	359	710/\$.ccls. and ((slot same (card device interface)) and ((plug\$3 swap\$3 insert\$3 add\$3 remov\$3 replac\$3) same (clock clk) and ((synchroniz\$5 synchronous) same bus)))	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2003/08/20 21:10
-	0	CH-00395-\$.did.	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2003/08/21 08:57
-	0	CH-9800395-\$.did.	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2003/08/21 08:57

-	0	CH-98/00395-\$.did.	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2003/08/21 08:57
-	2	("20010011313").PN.	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2003/08/21 14:06
-	12	710/301-304.ccls. and (phase near5 shift)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2003/08/22 09:43
-	159190	((insert\$3 swap\$3 plug\$3 remov\$3 replac\$3 add\$3 extract\$3) near6 slot)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/02/08 18:20
-	5803	(clock near5 select\$3) same synchron\$4	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/02/08 18:21
-	181	((insert\$3 swap\$3 plug\$3 remov\$3 replac\$3 add\$3 extract\$3) near6 slot)) and ((clock near5 select\$3) same synchron\$4)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/02/08 22:39
-	8	((insert\$3 swap\$3 plug\$3 remov\$3 replac\$3 add\$3 extract\$3) near6 slot)) same ((clock near5 select\$3) same synchron\$4)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/02/08 18:21
-	236679	analog near6 convert\$3	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/02/08 19:45
-	36	((insert\$3 swap\$3 plug\$3 remov\$3 replac\$3 add\$3 extract\$3) near6 slot)) and ((clock near5 select\$3) same synchron\$4) and (analog near6 convert\$3)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/02/08 22:39
-	95002	analog near6 input	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/02/08 22:39
-	181	((insert\$3 swap\$3 plug\$3 remov\$3 replac\$3 add\$3 extract\$3) near6 slot)) and ((clock near5 select\$3) same synchron\$4)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/02/08 22:48
-	12	(analog near6 input) and (((insert\$3 swap\$3 plug\$3 remov\$3 replac\$3 add\$3 extract\$3) near6 slot)) and ((clock near5 select\$3) same synchron\$4))	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/02/08 22:40
-	59	((insert\$3 swap\$3 plug\$3 remov\$3 replac\$3 add\$3 extract\$3) near6 slot)) same (analog near2 input)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/02/08 22:48
-	9	(US-6418492-\$ or US-6128682-\$ or US-6212580-\$ or US-6263305-\$ or US-6141711-\$ or US-6178474-\$ or US-6338107-\$ or US-6587909-\$).did. or (US-20010011313-\$).did.	USPAT; US-PGPUB	2004/09/02 08:22

-	103	((plug\$3 swap\$3 insert\$3 add\$3 remov\$3 replac\$3) near10 module) same (clock clk) same ((synchroniz\$5 synchronous) same bus)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/09/02 10:34
-	35	((plug\$3 swap\$3 insert\$3 add\$3 remov\$3 replac\$3) near10 module) same ((synchroniz\$5 synchronous) same bus) same ((clk clock) near10 (select\$3 control\$3))	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/09/02 10:33
-	8	((plug\$3 swap\$3 insert\$3 add\$3 remov\$3 replac\$3) near10 module) same slot same ((synchroniz\$5 synchronous) same bus) same ((clk clock) near10 (select\$3 control\$3))	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/09/02 10:33
-	2577	acquisition near3 module	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/09/02 10:33
-	1	((plug\$3 swap\$3 insert\$3 add\$3 remov\$3 replac\$3) near10 module) same ((synchroniz\$5 synchronous) same bus) same ((clk clock) near10 (select\$3 control\$3)) and (acquisition near3 module)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/09/02 10:34
-	2	((plug\$3 swap\$3 insert\$3 add\$3 remov\$3 replac\$3) near10 module) same (clock clk) same ((synchroniz\$5 synchronous) same bus) and (acquisition near3 module)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/09/02 10:35
-	2	((plug\$3 swap\$3 insert\$3 add\$3 remov\$3 replac\$3) near10 module) same (clock clk) same ((synchroniz\$3 synchron\$5 synchronous) same bus) and (acquisition near3 module)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/09/02 10:38
-	91	((plug\$3 swap\$3 insert\$3 add\$3 remov\$3 replac\$3) near10 module) same (clock clk) same ((synchroniz\$3 synchron\$5 synchronous) same bus)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/09/02 13:44
-	3	710/301-304.ccls. and (((plug\$3 swap\$3 insert\$3 add\$3 remov\$3 replac\$3) near10 module) same (clock clk) same ((synchroniz\$3 synchron\$5 synchronous) same bus))	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/09/02 15:57
-	5407	(clock clk) near10 ((synchroniz\$3 synchron\$5 synchronous) same bus)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/09/02 13:45
-	587	(clock clk) near10 ((synchroniz\$3 synchron\$5 synchronous) same bus) same module	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/09/02 13:45
-	82780	((plug\$3 swap\$3 insert\$3 add\$3 remov\$3 replac\$3) near10 module)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/09/02 13:46
-	256	((clock clk) near10 ((synchroniz\$3 synchron\$5 synchronous) same bus) same module) and (((plug\$3 swap\$3 insert\$3 add\$3 remov\$3 replac\$3) near10 module))	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/09/02 13:46
-	3	710/301-304.ccls. and (((clock clk) near10 ((synchroniz\$3 synchron\$5 synchronous) same bus) same module) and (((plug\$3 swap\$3 insert\$3 add\$3 remov\$3 replac\$3) near10 module)))	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/09/02 13:46

-	58	710/\$.ccls. and (((clock clk) near10 ((synchroniz\$3 synchron\$5 synchronous) same bus) same module) and (((plug\$3 swap\$3 insert\$3 add\$3 remov\$3 replac\$3) near10 module)))	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/09/02 15:16
-	4	361/\$.ccls. and (((clock clk) near10 ((synchroniz\$3 synchron\$5 synchronous) same bus) same module) and (((plug\$3 swap\$3 insert\$3 add\$3 remov\$3 replac\$3) near10 module)))	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/09/02 14:58
-	0	326-327/\$.ccls. and (((clock clk) near10 ((synchroniz\$3 synchron\$5 synchronous) same bus) same module) and (((plug\$3 swap\$3 insert\$3 add\$3 remov\$3 replac\$3) near10 module)))	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/09/02 14:58
-	7	326/\$.ccls. and (((clock clk) near10 ((synchroniz\$3 synchron\$5 synchronous) same bus) same module) and (((plug\$3 swap\$3 insert\$3 add\$3 remov\$3 replac\$3) near10 module)))	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/09/02 15:02
-	10	327/\$.ccls. and (((clock clk) near10 ((synchroniz\$3 synchron\$5 synchronous) same bus) same module) and (((plug\$3 swap\$3 insert\$3 add\$3 remov\$3 replac\$3) near10 module)))	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/09/02 15:14
-	845	(synchron\$5 near10 independ\$4) same connect\$3	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/09/02 15:15
-	1	((synchron\$5 near10 independ\$4) same connect\$3) and (((clock clk) near10 ((synchroniz\$3 synchron\$5 synchronous) same bus) same module) and (((plug\$3 swap\$3 insert\$3 add\$3 remov\$3 replac\$3) near10 module)))	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/09/02 15:15
-	30	711/\$.ccls. and (((clock clk) near10 ((synchroniz\$3 synchron\$5 synchronous) same bus) same module) and (((plug\$3 swap\$3 insert\$3 add\$3 remov\$3 replac\$3) near10 module)))	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/09/02 15:16
-	9	710/301-304.ccls. and (((plug\$3 swap\$3 insert\$3 add\$3 remov\$3 replac\$3) near10 (card board adapter module)) same (clock clk) same ((synchroniz\$3 synchron\$5 synchronous) same bus))	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/09/02 16:06
-	15	710/301-304.ccls. and (((plug\$3 swap\$3 insert\$3 add\$3 remov\$3 replac\$3) same (card board adapter module pci cpci (compact adj pci))) same (clock clk) same ((synchroniz\$3 synchron\$5 synchronous) same bus))	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/09/02 17:57
-	69	710/301-304.ccls. and (card board adapter module pci cpci (compact adj pci)) same (clock clk) same ((synchroniz\$3 synchron\$5 synchronous) same bus)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/09/02 17:56
-	312	(card board adapter module pci cpci (compact adj pci)) same (clock clk) same ((synchroniz\$3 synchron\$5 synchronous) same bus) same (connector slot)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/09/02 17:57
-	24	(((plug\$3 swap\$3 insert\$3 add\$3 remov\$3 replac\$3) same (card board adapter module pci cpci (compact adj pci))) same (clock clk) same ((synchroniz\$3 synchron\$5 synchronous) same bus)) same (slot connector) same (external internal)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/09/02 18:39